

- iii) In Tamalu village – main road goes to Graveyard via Church about 1KM distance

Estimate for construction of rural road from main road to Tamalu via Elpanam and church (1.0 KM) is under process.

#### **Infrastructure for Roads.**

- i) Road Roller is too old – replacement necessary

Survey report for the unserviceable Road Roller is under process. As soon as the survey report is sanctioned, procurement action for new Road Roller will be initiated.

- ii) Old Jeep – AN-1649 – Condemnation survey report submitted.

Action for replacement of the jeep is under process.

#### **Drinking Water**

- i) Old 9 water pump available

Pumps are in working condition

- ii) Water pumps 50-52 years old Models are absolute, spare parts not available.

Wherever necessary, action is being taken to replace old pumps with new ones.

- ii) Insufficient to meet the present requirement