EX STATUS RØ22 23/10/99 Ø1:04:58

ERC. . .

RØ22 23/10/99 Ø1:Ø4:58

K42 DE N60 Z 2

TO. ESAAJVS P/B INFO. DIR. (TW) PAB FM. PLANTATION INCHARGE SOUTHBAY L/A

22/10/99 NO. MD/10

= THE RCC BRIDGE AT HARMINDER BAY HAS BEEN DAMAGED VERY BADLY () DIFFICU LTIES ARE BEING EXPERIENCED TRANSPORTATION OF RATION ARTICLES AND ONGES TO PHC HUTBAY FOR PERIODICAL MEDICAL CHECK UP () KINDLY PERMIT TO HIRE ENGINE DINGHI FOR TRANSPORTATION PURPOSE () MATTER MAY BE TAKEN UP WITH CONCERNE D HIGHER AUTHORITY FOR IMMEDIATE REPAIR OF THE BRIDGE () FOR KIND INFO. PS F ==

1855...

084423 h