

6655/V

mug

Z₂

2 169 90

16-5/16 A.C NRSE (E.L.) Prothapur P/S
 W- E.S AAJSYS P/S
 Pm S.W S/Island
 274 22/1

AAJS	
1. R. D. No.:	2260
2. Date:	25-1-01
3. To Whom Marked:	AAJS
4. Remarks:	
5. Initials of E.S.:	

2 KRYA no. 135 dtd 20/1/01 @ Unit No. 1
 have not in function since 17/1/2001
 Technician reached S/Island and
 Rectified the fault ~~with~~ which
 lasted for 3 days (i) PARA (i) most
 of the point connected with unit
 no. 2 and 3 are not functioning due
 to defected ~~in~~ tube and some for
 inverter (i) Request to arrange replacement
 of these tube and inverter meant
 deputing technician to S/Island (i) Present
 requirement in 20 nos. tube & inverter ~~and~~
 as reported SPP attendant (i) for info.
 & N/A ple

de/
 Enlist

In 0810/22
 P/S

OPW