K42/N60 Z 16 53 SC NO GR

TO ES AAJVS P/B
INF TEHSILDAR L/A
FM P I/C 0/S SOUTH BAY

54/98 16/10/98

=D/6 SET NOT OPERATED SINCE 06/X/98[.] SELF DISCUSSED WITH A.E ELE HUT BA
Y[.] TECHNICIAN WAS ALREADY DUPTED ON DUTY AND NEW DG SET MAY BE INSTALLED
YI.] TECHNICIAN WAS ALREADY DUPTED ON DUTY AND NEW DG SET MAY BE INSTALLED
AT S/BAY AS INFORMED BY A.E[.] HOWEVER NO TECHNICIAN YET BEEN REACHED S/
BAY TO REPAIR THE SET[.] FOR INFO AND N/A PSE=

1800

MAB..

MAB..