

(81) (21)

File No. IV-21/AATVS/98

et

Subject:

Construction & Maintenance of Bldg at HQ.

Para
No.

-1-

① It is observed that the space available inside the Adibasera is not sufficient for the stay of tribals. Space are available in the back yards for extension and making the building to a two-storied one. At the same time urgent repairs and re-wiring of the Adibasera is required to avoid and prevent any sort of mishap.

② The surroundings of Adibasera is to be cleaned to prevent diseases. we can plant flower plants etc., to keep the area beautiful.

③ At the same, it is also felt that the AASUS office space is not sufficient to carry out the daily affairs smoothly. The building area could be modified by covering the verandah with the chamber of E.S.