

Note Sheet

Subject

File .....5-5/HQ/AAJVS/TW.9.....

-160-

Para No.	
280	<p>An amount of Rs.9,85,082/- was sanctioned towards renovation of AAJVS office building. The work was completed during 2013. The roofing work was not carried out properly and several complaints were made to the office of Junior Engineer situated in Secretariat.</p>
281	<p>Instead of repairing the fault, the officials place a small paint bucket beneath the sheet where water is seeping. During rain, the bucket over flows and water is spread all over the room. Due to recent rain, several documents, files and records were damaged due to this leakage. The officials are finding it difficult to discharge their duties.</p>
282	<p>It is proposed to send a letter to Assistant Engineer (Works), APWD for immediate repair of the fault. Draft letter added please.</p>

8/7/14

Recd

8/7/14

AAJVS