

148

MOST URGENT

F. No 5-5/HQ/AAJVS/TW-98/372
**OFFICE OF THE EXECUTIVE SECRETARY
ANDAMAN ADIM JANJATI VIKAS SAMITI
SECRETARIAT COMPLEX, PORT BLAIR**

Dated the 25/ September, 2006.

To

The Executive Engineer,
Port Blair South Division,
APWD, Port Blair.

Sub : Leakages / water floating to office room - reg.

Sir,

I am to refer to this office letter No. 5-5/AAJVS/98/1370 dated 06th December, 2005 and Letter No. 5-5/AAJVS/2006 dated 24th August, 2006 [copies enclosed] and to say that the Office building of Andaman Adim Janjati Vikas Samiti Secretariat Complex was renovated with new Asbestos sheets during the month of March, 2006.

But it is to regret to mention here that the Chamber of Executive Secretary and office rooms are leaking badly and Officials are not able to perform their daily duties. Mats provided in the room has been wet badly and is omitting bad smell. New sets of Computers were installed but electrical short circuit has destroyed the same.

It is therefore requested to kindly look into the matter for immediate replacement of roof or temporary measures to stop the leakage of the roof.

Yours faithfully

Encl. : As above

[Signature]
25/9/06
**Executive Secretary
AAJVS**

Copy to :

- 1 SE, APWD, Port Blair for information and necessary action please.
- 2 Secretary [TW], A&N Administration, Port Blair.

[Signature]
25/9/06
**Executive Secretary
AAJVS**

*Received
P. K. K. K.
25/9/06*

*Received
Jm
25/9/06*

a/c