

225
This is to inform that the roof of AAJVS Office is very badly leaking and damaging the records kept in the Office. Further, it is very difficult to sit inside the rooms. Due to limited space in the Office, we are facing many problems in smoothly functioning the daily routine Office affairs, especially during this Monsoon season.

226
Secondly, the door and windows of the small store room is deteriorated and requires immediate repairs/replacement. Important Office properties are kept in the store room and if the present condition of the doors and windows persists, there are chances of theft.

227
Thirdly, AAJVS has only two rooms for undertaking our routine Office affairs. In the ground floor, we have two rooms as toilet and bath rooms totally abandoned. The rooms cannot be used as it requires major repair, cleaning, fixing of new doors and ventilators.

228
Since, the toilet room of our parent department is being used, it is proposed that the above mentioned two rooms may be modified, repaired and converted into a single big store room, which is very much required to keep all our valuable Office assets

229
AAJVS was constituted in 1976, but till date no documentation of any kind of events has been made. Rather due to the prevailing technology of that time was as such that it was hardly possible. But now, it has changed, with computerisation of events in the form of CD's, videos, audios etc, we can preserve our records for centuries. In this context, it is proposed that the existing store room can be modified after repairs into a good library-cum-reference rooms, where we can preserve our documents, procure good books published all over the world in the tribes and also keep all kinds of documents.