

(101)

This is regarding repairs, maintenance of office building of AAJVS and fixing of tiles in the Chamber of Executive Secretary, Office room. The mat earlier fixed in the Chamber of Executive Secretary have been fully damaged and forced to remove due to leakage of roofing. After removal of the mat from the chamber of Executive Secretary is look not good and it requires necessary modification.

(102)

The entire office area including rooms and corridor is around 120 Sq. Mtrs. The attached building of the Directorate of Tribal Welfare is fully floored with white tiles / mosaic. If the office of the attached building i.e. of AAJVS is also flooring with white tiles will make a uniform look.

(103)

It is proposed that if approved we may request to Executive Engineer, PBSO, APWD to undertake the work under head Repairs and Maintenance of building.

(104)

Here it is mentioned that replacement of roof, ceiling, white washing / painting etc of the building of AAJVS during the past year has been met out of the fund of APWD under PBSO, Division.

(105)

Director [TW] is the competent authority to approve the proposal.

Submitted for approval please.

Do
7/11

Ex. Secy

7/11/06

Dir (TW)

Please indicate the estimated expenditure.

(106)

Also quote the relevant item (S.E.No.) of Delegation of powers to the functionaries of AAJVS.

Miranda
7-11-2006

Es

5711/Dir TW
7/11/06