

2. NO 168

(78) (3)

No. 1-50/PPS&W/Steno/99/1946
OFFICE OF THE EXECUTIVE ENGINEER(PPS&W)
Electricity Department.

Port Blair, dated the 29 July 99

To
The Director(Tribal Welfare),
A&N Administration,
Port Blair.

Sub:- Repairing of street lights - payment of energy charges for the streetlights installed at Harmander Bay - reg.

Sir,

Kindly refer to discussion held at Little Andaman on 24.7.99 when Hon'ble Chief Secretary has desired that the street lights repairing as well as payment of energy charges for Harmander Bay tribal settlement to be taken care by the Tribal Welfare Directorate.

Out of 33 streetlights (18 sodium vapour and 15 flourecent sets) fitted, only four (2 each type) are working and for repair of the other 29 sets, materials as per list are required.

This matter was discussed with the Superintending Engineer(Elec) after my return ffrom tour and as per Superintending Engineer(Elec) in case your Directorate agrees 16 sets sodium vapour lamps can be repaired by using materials available with this department and the charges for the same to be paid by your directorate. For repairing of flourscent lamp sets, the spares are required to be arranged which are not available in our department and it is requested to kindly take necessary action.

Yours faithfully,

(S.V. KRISHNA)

Executive Engineer(PPS&W)

Encl: One

Copy is forwarded to:-

1. The Superintending Engineer, Electricity Department, Port Blair for information.
2. The Assistant Engineer(Elec), Hut Bay for information and necessary action.

Executive Engineer(PPS&W)

