7. A wider approach path from the jetty to new location be laid to enable the movement of tricycle so that the ration aricles and other goods can be transported from jetty to the settlement conveniently.

8. Effective drainage be provided for the entire settlement and for the approach path.

(Executive Secretary)

alterney released because at Steril Island for the

Embly can left prices that two left many the manual flag

10

carcerned.