SIGNAL

152

. To :

Assistant Engineer (Electricity),

Hut Bay.

Info:

Social Worker, Dugong Creek.

From:

Executive Secretary,

AAJVS, Port Blair

No. 16-5/AAJVS/TW-98/565

Date: 28/09/2000

It is reported that both the DG sets installed at Dugong Creek is not functioning for the last three days and the tribals are expressing their anguish over the continue power failure (.) Request to depute staff to rectify sets and to supply the power at the settlement (.)

Executive Sections,

5/c