=THE SBEO HAS REPORTED THAT TWO NOS OF SOLAR PANNELS ARE MISSING FROM THE SOLAR PLANT. MATER WAS ENQUIRED AMONG THE LOCAL STAFF AT D/CREEK. NO ON E HAS CAME FORWARD TO TAKE THE RESPONSIBILITIES OF MISSING SOLAR PANNEL. HOWEVER EFFORTS ARE BEING MADE TO FINDOUT THE FACT. FOR INFO PSE=

RKN

0740

0815/15/1