- 165

No:1-190/NRSE/Ele/01/ | 880
Office of the Executive Engineer(NRSE)
Electricity Department
Prothrapur

207

Prothrapir dated the

14 Sept., 2001

To

2419

The Executive Engineer(PPS&W), Electricity Department, Port Blair.

1. R. 2. D. I. 3. To What Mar 2=0 4. Remails 5. Initials of 1

Sub: - Missing of 2 Nos S.P.V. Pannels - Regd.

Sir,

It is reported by the social worker at Dugong Creek that 2 Nos pannels are found missing from the SPV Plants at Dugong Creek. In this connected we have requested vide T.O.No.1-190/NRSE/Ele/1840 dated 18/9/2001 to post Shri. G.Papa Rao, Regular Mazdoor stationed at Hut Bay to look after SPV plant at Dugong Creek. Now it seems that Shri. G.Papa Rao, Regular Mazdoor has not rurned up in spite of Executive Engineer(PPS&W) No.2-1715/Estt/2001-02/SG/2287 dated 28/8/01 addressed to Assistant Engineer, Hut Bay and copy endrosed to this office.

Hence it is requested that Assistant Engineer, Hut Bay may please be directed to enquire the matter and a suitable action may kindly be taken under intimation to this office. Copy of signal received from . S.W. Dugong Creek is enclosed for reference please.

Yours faithfully,

csd-

Encl: A/A.

Executive Engineer(NRSE)

Copy to:-

- 1/ Executive Eccretary AAJVS Port Blair for information.
- 2. The Assistant Engineer, NRSE-II for information.
- 3. The Junior Engineer(WES) to make ready to send Men along with materials to attend the SPV plant at Dugong Creek.

Executive Engineer(NRSE)