

(29)

No. 1-29/AAJVS/95-TW/ 213
ANDAMAN AND NICOBAR ADMINISTRATION
ANDAMAN ADIM JANJATHI VIKAS SAMITI
PORT BLAIR.

nd
22

Port Blair, dated the Aug., 1995.

To

The Executive Engineer,
P.B.S.D.
Port Blair.

Sub :- Maintenance of office building of AAJVS in
Secretariat Complex- Reg.

- - -

Sir,

Please refer to this office letter No.1-29/AAJVS/93-TW/
890 dt. 13.3.95 (Copy enclosed) on the above mentioned subject.

In this connection it may be pointed out that the
maintenance/repair works have not yet been carried out. In
addition, the pipe fitting have also become defective as a
result of which, all water of over head tank is drained.

You are, therefore, requested to arrange maintenance/
repair of the office building at the earliest.

Yours faithfully,

sd/-
Executive Secretary,
AAJVS.

Copy to the Chief Engineer, A.P.W.D for information.

Received

25/8/95

9c
Executive Secretary,
AAJVS.
17/8
16/9