

No.5-5/AAJVS/2003/ 347  
OFFICE OF THE EXECUTIVE SECRETARY  
ANDAMAN ADIM JANJAITI VIKAS SAMITI

Port Blair, Dated the 16 June, 03.

To

The Executive Engineer,  
Port Blair South Division,  
APWD, Port Blair

Sir,

I am to say that the Office building of Andaman Adim Janjati Vikas Samiti standing on the Secretariat Complex required ~~some~~ repairs. The doors and windows of the building are in defective. None of the windows having hook for the protection from wind and rain.

I am, therefore request you to depute one of your site engineer to inspect the building for repair and maintenance.

Yours faithfully,

Executive Secretary

O/c

13/6