

(42)

Pilpillow	There is no Head Master Secondary School	DE to post Head Master (Secondary) School Action : Director (Edn)
	One room Teachers quarters (10 Nos) are in dilapidated condition.	The quarters were seen by Secretary (Edn). There is an urgent need for repair of teacher quarters. Action : CE (PWD)
	The School building needs urgent renovation.	AE(PWD) informed that estimate has been prepared for renovation. The work should be implemented on priority. Action : CE (PWD) ; Director (Edn)
	Posting of regular science teacher	Director of Education to look into it. Action : Director (Edn)
Kamorta	The work for AEO Building to taken up immediately	It was informed that the work has been sanctioned. The building is to constructed in place of exiting AEO building. It was informed that write-off sanction has also been given. The work should be completed on priority. Action : CE (PWD)
	2 type III quarter to be started immediately	AEO informed that land has been identified. The proposal may be moved to AC(Nancowry) for allotment of land for construction of quarters. Action : DC (C/N) ; Director (Edn)
	4 Nos Class rooms have been sanctioned but consruction has not started..	3 classrooms have been constructed earlier. The foundation has been laid for double storeyed building. The three classrooms can be constructed as a second storey. It was decided that we may not construct 4 class room separately. Action : CE (PWD)