

There is no complaint from any village for insufficient supply.

iv) Untreated water is supplied

The water supply is through wells. As per the quantity of raw water in wells, adequate chlorination is being done before supply. Action is also being taken for construction of filter unit at headquarter area Malacca, Perka and part of Tamalu.

v) Public Hydrant-1/2 inch connection for 60-hundred people.

As desired by the villagers, extra public hydrants are being provided and will be completed by the end of January 2003.

vi) Long queue for collection of water

There is no queue for collection of water. However action will be taken to provide more public hydrants

vii) Govt. quarters having pipe water line

All government quarters are provided with piped water supply

viii) As per Test Report sufficient water available for supply to balance quarters

No complaint from any source, so far. It will be attended to if received.

ix) In interior village no pipe line and no well

Recently some habitats have come up in the interior village. The village Captain have been requested to furnish the details with regards to hutments / dwelling. Action will be taken immediately for providing water supply.